
# CASE STUDY



### **HAYLEY DEXIS**

### **BEARINGS // AGGREGATES**

Focus on value



### THE SITUATION

The customer, a national aggregates company, had suffered a bearing failure within a critical application at their quarry in an isolated corner of Western Scotland.

The failure occurred at the tail-end of the night shift on a Monday morning, with it being reported to the nearest HAYLEY DEXIS branch at 07:20am.

### THE SOLUTION

The call was answered by the team at the Inverness branch of HAYLEY DEXIS, with the bearing at the heart of the issue being identified quickly as a 60mm Cooper® Split Bearing Unit.

The branch utilised their widereaching stock-holding and were able to provide a direct replacement off-the-shelf. Despite the remoteness of the customers' site, a substantial drive away from the branch, the new bearing reached the quarry by 1:00pm.

# KEY VALUE AREAS SERVICES INCOME

This enabled the customer to get their operation back up and running quickly.

### THE RESULT

The quarry was operational again in-time for the beginning of the night shift on the Monday evening. If it had not been for the stock and fast service of HAYLEY DEXIS Inverness, the customer would have encountered a number of serious operational problems



representing a total £12.5k cost, including:

- Immobilised and non-productive machinery.
- Loss of night-coated material supply for whole shift.
- Cancellation of a complete work shift, meaning loss of work for contractors.
- Trucks and drivers sitting in-wait, resulting in a loss of productivity.

## **CONTACT US!**

Speak to your local HAYLEY DEXIS branch today!

You can find their details by using our online Branch Finder tool:

www.hayley-group.co.uk/branch-finder.

### **KEY BRANDS**



### **KEY SOLUTIONS**

SKF Cooper® 60mm split spherical roller bearing.

### **KEY RESULTS**

£12.5k in downtime-related costs avoided.

Operations reinstated in time for commencement of the night shift.



