

CASE **STUDY**

HAYLEY DEXIS

**HELP TO MINIMISE
DOWNTIME AT
QUARRY IN NORTH
WALES**

CS070



HAYLEY
DEXIS

HAYLEY DEXIS DRIVES // AGGREGATES

Focus on **value** **TRACK
UP**

THE SITUATION

A quarry in North Wales had suffered a failure to a shaft-mounted speed reducer drive on site. The breakdown had caused one of the customers' conveyor applications to grind to a complete halt, meaning productivity was taking a hit with every passing hour.

THE SOLUTION

The call came into the customer's local HAYLEY DEXIS branch, in Oswestry, who worked with the expert in-house drives team to source a solution quickly.

Instead of a like-for-like replacement, the teams collaborated to settle on a new and improved direct drive which was delivered to the quarry the very next day.

KEY VALUE AREAS



INCOME

The rapid turnaround was enabled by HAYLEY DEXIS stock, as having the required motor delivered from the manufacturer, in addition to the gearbox, would have added to the lead time.

THE RESULT

Thanks to the in-depth product knowledge of the HAYLEY DEXIS teams, as well as an understanding of the customers' application, the new direct drive will enhance the reliability and performance of the operation.

“

THE NEXT-DAY
SERVICE SAVED THE
CUSTOMER FROM A
COSTLY PERIOD OF
DOWNTIME.

”

The potential for a lengthy period of downtime, which would have had a significant impact on productivity, was eradicated by the next-day service provided.

The on-shift Quarry Manager was thrilled with the outcome of the work.

CONTACT US!

Speak to your local HAYLEY DEXIS branch today!

You can find their details by using our online Branch Finder tool:

www.hayley-group.co.uk/branch-finder.

KEY RESULTS

Downtime minimised.

More modern drive system enabled.

Energy efficiency improved.





HAYLEY

DEXIS